

**Stormwater Treatment Measures and Hydromodification Management Controls
Installed within San Mateo County
from July 1, 2018 through June 30, 2019**

The following pages include listings of stormwater treatment measures and any hydromodification controls that were installed in the jurisdictions within San Mateo County from July 1, 2018 through June 30, 2019.

A table is provided for each agency in which stormwater treatment measures and/or HM controls were installed during this timeframe. Some tables also list facilities that were installed prior to this timeframe. Tables are provided for the following agencies:

- Belmont
- Burlingame
- Colma
- Daly City
- Foster City
- Half Moon Bay
- Menlo Park
- Millbrae
- Redwood City
- San Bruno
- City of San Mateo
- County of San Mateo (Unincorporated)
- South San Francisco

The following agencies had no stormwater treatment measures or HM controls installed from July 1, 2018 through June 30, 2019, and therefore no table is provided for:

- Atherton
- Brisbane
- East Palo Alto
- Hillsborough
- Pacifica
- Portola Valley
- San Carlos
- San Mateo County Flood Control District
- Woodside

C.3.h.v.(2). ► Table of Newly Installed³³ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible ³⁴ For Maintenance	Type of Treatment/HM Control(s)
Merry Moppet School	2200 Carlmont Drive	Merry Moppet School	Bio-retention
400 El Camino Real Condo	400 El Camino Real	400 El Camino Real Homeowner Association	Bio-retention

³³ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.

³⁴ State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2). ► Table of Newly Installed³³ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible³⁴ For Maintenance	Type of Treatment/HM Control(s)
The Trousdale – Assisted Living and Memory Care Center	1600 Trousdale Drive	Peninsula Health Care District	Bioretention area, permeable pavement, flow-through planter
Public Parking Lot H	225 El Camino Real	City of Burlingame	Bioretention area
California Drive Roundabout	California Drive at Bellevue Avenue	City of Burlingame	Bioretention areas

³³ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.

³⁴ State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2). ► Table of Newly Installed³³ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible³⁴ For Maintenance	Type of Treatment/HM Control(s)
Town Hall Renovation	1198 El Camino Real	Town of Colma	Bioretention Areas

³³ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.³⁴ State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2). ►Table of Newly Installed³³ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Name of Facility	Address of Facility	Party Responsible ³⁴ For Maintenance	Type of Treatment/HM Control(s)
Garden Valley Residential Subdivision	317 Second Avenue	Homeowners Association	Biotreatment areas (flow-through planter)

³³ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.
³⁴State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2). ► Table of Newly Installed³³ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Name of Facility	Address of Facility	Party Responsible ³⁴ For Maintenance	Type of Treatment/HM Control(s)
The Triton (formerly "The Waverly")	55 Triton Park Lane	Areof VI US Pilgrim-Triton	Flow-Through Planter; Vegetated Buffer Strip; Permeable Pavers, Turf Block
BioMed/Illumina	200 Lincoln Centre Drive	BMR-Lincoln Centre LP	Bioretention area

³³ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.

³⁴ State the responsible operator for installed stormwater treatment systems and HM controls.

Permittee Name: _____

C.3.h.v.(2). ► Table of Newly Installed³⁴ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible³⁵ For Maintenance	Type of Treatment/HM Control(s)
Cameron's Best Western	1410 S. Cabrillo Highway	Palmer Enterprises (Cameron Palmer)	Bioretention Area
Half Moon Bay Library Replacement Project	620 Correas Street	City of Half Moon Bay	Bioretention Areas, Permeable Pavers, Green Roof
Half Moon Bay High School Track and Field Improvements*	1 Lewis Foster Drive	Cabrillo Unified School District	Bioretention Area
Correas Street / Purissima Street Safe Routes to School and GI Project*	Intersection of Correas Street and Purissima Street	City of Half Moon Bay	Bioretention Areas
Pacific Ridge Subdivision*	End of Terrace Avenue (Lat: 37.477, Long: -122.429)	City of Half Moon Bay	Bioretention Swale

*Non-Provision C.3 Regulated Project

³⁴ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.³⁵ State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2). ► Table of Newly Installed³³ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible ³⁴ For Maintenance	Type of Treatment/HM Control(s)
Menlo Park Hotel	1400 El Camino Real	POLLOCK 1400 EL CAMINO REAL, LLC	11 Treatment filter 1 Flow-thru planter
Marquis	133 Encinal Avenue	Pulte Home Company, LLC	7 Bio-retention

³³ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.

³⁴ State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2). ► Table of Newly Installed³⁵ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible³⁶ For Maintenance	Type of Treatment/HM Control(s)
Green Hills Golf Course	500 Ludeman		3 Vortex Separators
Private residence	1 Alp Way		Vegetated Swale (Bio-Swale)

NOTE: There were no regulated newly installed stormwater treatment systems facilities to report for FY 2018-2019.³⁵ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.³⁶ State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2). ► Table of Newly Installed³³ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

#

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible ³⁴ For Maintenance	Type of Treatment/HM Control(s)
Burger King	575 El Camino Real	Property Owner	Bioretention Area
1305 El Camino Real	1305 El Camino Real	Property Owner	Media Filters and Vault Detention System
150 El Camino Real	150 El Camino Real	Homeowners Association	Bioretention Area and Detention Pipes
Stanford Clinics	420/450 Broadway	Property Owner	Media Filter & Bioretention Areas
Stanford Redwood City	485 Broadway	Property Owner	Bioretention Areas
700/720/740 Bay Road	700/720/740 Bay Road	Property Owner	Bioretention Areas
1629 Main Street	1629 Main Street	Property Owner	Bioretention Areas
2215 El Camino Real	2215 El Camino Real	Property Owner	Bioretention Areas
Carlsen Porsche	3636 Haven	Property Owner	Pervious Pavement
849 Veterans	849 Veterans	Property Owner	Bioretention Areas & Pervious Pavements
CA National Guard Armory	939 Valota Road	City	Bioretention Areas
1100/1600/1900 Seaport Blvd	1100/1600/1900 Seaport Blvd	Property Owner	Bioretention Areas
Oracle	10 Twin Dolphin	Property Owner	Bioretention Areas

³³ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.

³⁴ State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2). ► Table of Newly Installed³³ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information. **Guidance:** The table is intended to provide a list of all newly installed treatment measures and HM controls to vector control agencies on an annual basis before the wet season (i.e., October 1). Countywide Programs (or in some cases, individual Permittees) will submit these tables to vector control agencies to fulfill this requirement. The facility name, address, responsible party and type of treatment/HM control should be provided for all facilities installed during this fiscal year. Do not leave any cells blank.

Name of Facility	Address of Facility	Party Responsible ³⁴ For Maintenance	Type of Treatment/HM Control(s)
Aperture	406 San Mateo Ave	San Bruno Plaza, LLC	Flow-Through Planters / Contech Stormfilter with 3 Cartridges
841 San Bruno Ave	841 San Bruno Ave	MSD-DV San Bruno, LLC	Flow-Through Planters / Permeable Paving
SF Police Credit Union	1250 Grundy Lane	SF Police Credit Union	Flow-Through Planters / Permeable Paving

³³ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.

³⁴ State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2). ► Table of Newly Installed³⁶ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible³⁷ For Maintenance	Type of Treatment/HM Control(s)
California Water Service - Bayshore Operations Center	341 N. Delaware St.	California Water Service	Bioretention/permeable pavers
Promenade Townhomes	220 N. Bayshore Townhomes	Promenade Townhomes HOA	Bioretention

³⁶ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.³⁷ State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2). ► Table of Newly Installed³⁵ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible³⁶ For Maintenance	Type of Treatment/HM Control(s)
Parking lot/Road Improvements at La Honda Creek Open Space Preserve	900 Sears Ranch Road	Property Owner	Bioretention
Abolmoluki Minor Subdivision	175 & 205 Glen Aulin Lane, Burlingame	Property Owners	Flow-through planter
Kwitowski Minor Subdivision	888 Berkeley Ave.	Property Owner	Pervious Pavers
Middlefield Road Parking Lot	3060 Middlefield Road	County Public Works	Bioretention area

³⁵ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.

³⁶ State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2). ► Table of Newly Installed³³ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible ³⁴ For Maintenance	Type of Treatment/HM Control(s)
Costco Gas Station	479 S. Airport Blvd., South San Francisco, CA	Costco Wholesale Corporation	Filterra Bioretention Area (1)
Genentech Building 40	600 E. Grand Ave., South San Francisco, CA	Genentech, Inc.	Bioretention Areas (12)
Home 2 Suites	550 Gateway Blvd., South San Francisco, CA	Sri Krishna Enterprises	Bioretention Areas (3)
HCP Life Sciences	201-225 Gateway Blvd., South San Francisco, CA	Britannia Gateway II, LP c/o HCP, Inc.	Bioretention Areas (5) Self-retaining areas (3)
Miller Senior Housing	300 Miller Ave., South San Francisco, CA	Rotary Miller Avenue LLC	Flow-through Planters (4), Media Filter (1)
Park SFO	195 North Access Rd., South San Francisco, CA	Robert Simms (Property Owner)	Bioretention Areas/planters (8)
Costco Gas Station	1600 El Camino Real, South San Francisco, CA	Costco Wholesale, Inc.	Bioretention Areas (10)
USDA Building	560 Eccles Ave., South San Francisco, CA	SMPO ELS, Inc.	Bioretention Area (1), Self-treating area (1)

³³ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.

³⁴ State the responsible operator for installed stormwater treatment systems and HM controls.