

**Stormwater Treatment Measures and Hydromodification Management Controls
Installed within San Mateo County
from July 1, 2015 through June 30, 2016**

The following pages include listings of stormwater treatment measures and any hydromodification controls that were installed in the jurisdictions within San Mateo County from July 1, 2015 through June 30, 2016.

A table is provided for each agency in which stormwater treatment measures and/or HM controls were installed during this timeframe. Some tables also list facilities that were installed prior to this timeframe. Tables are provided for the following agencies:

- Burlingame
- East Palo Alto
- Foster City
- Hillsborough
- Menlo Park
- Millbrae
- Redwood City
- San Carlos
- City of San Mateo
- South San Francisco
- Unincorporated County of San Mateo

The following agencies had no stormwater treatment measures or HM controls installed from July 1, 2015 through June 30, 2016, and therefore no table is provided for:

- Atherton
- Belmont
- Brisbane
- Colma
- Daly City
- Half Moon Bay
- Pacifica
- Portola Valley
- San Bruno
- San Mateo County Flood Control District
- Woodside

C.3.h.v.(2) ► Reporting Newly Installed Stormwater Treatment Systems and HM Controls (Optional)

On an annual basis, before the wet season, provide a list of newly installed (installed within the reporting year) stormwater treatment systems and HM controls to the local mosquito and vector control agency and the Water Board. The list shall include the facility locations and a description of the stormwater treatment measures and HM controls installed.

City of Burlingame information will be submitted separately in a San Mateo Countywide Pollution Prevention Program submittal directly to local vector control agency.

Name of Facility	Address of Facility	Party Responsible ² For Maintenance	Type of Treatment/HM Control(s)
The Trousdale 25-unit residential condominiums	1800 Trousdale Drive	Property Owner	Flow-through planters, porous asphalt pervious paving
Sunrise Assisted Living (Pre-MRP 1.0) <u>Note:</u> This facility was actually installed in the previous FY 14-15; however, it was inadvertently not reported in the Annual Report for that year. Therefore, it is included here in order to ensure that it is reported to the Regional Water Board and the Vector Control District.	1818 Trousdale Drive	Property Owner	Vortex hydrodynamic separator

²State the responsible operator for installed stormwater treatment systems and HM controls.

East Palo Alto

C.3.h.v.(2). ► Table of Newly Installed¹ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible ² For Maintenance	Type of Treatment/HM Control(s)
Montage/ Edenbridge Homes/ DKB Homes—51 Unit Subdivision	2485 PULGAS AVENUE, EAST PALO ALTO, CA	HOA	5-Infiltration Trenches 6- Bioretention Areas 6 -Flow-Through Planters
Menlo Park Fire Protection District (MPFPD) Fire Station #2	2290 University Avenue East Palo Alto, CA	MPFPD	1- Storm Water Drop Inlet with Diverter Valve 1-Stormdrain Manhole with Contech System Filter Cartridges 1-Storm Water Tank Detention Basin 2-Bioretention Landscaped Areas 2-Trench Drains

¹ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.

²State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2). ► Table of Newly Installed⁴¹ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible ⁴² For Maintenance	Type of Treatment/HM Control(s)
Gilead – New Building & Parking Garage	355 Lakeside Dr.	Gilead Sciences	Bio-retention
Triton Pointe	558 Pilgrim Dr.; 551 Foster City Blvd.; 1125 E. Hillsdale Blvd.	Thompson/Dorfman	Bio-retention; Flow-through planter; Filter Vault Units

⁴¹ “Newly Installed” includes those facilities for which the final installation inspection was performed during this reporting year.⁴² State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2). ► Table of Newly Installed⁴⁰ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible⁴¹ For Maintenance	Type of Treatment/HM Control(s)
The Nueva School	6565 Skyline Blvd	Property Owner	Bio-retention area
The Nueva School	6565 Skyline Blvd	Property Owner	Pervious Concrete

⁴⁰ “Newly Installed” includes those facilities for which the final installation inspection was performed during this reporting year.⁴¹ State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2). ► Table of Newly Installed⁴¹ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible ⁴² For Maintenance	Type of Treatment/HM Control(s)
Sharon Heights Golf and Country Club	2900 Sand Hill Rd	Sharon Heights Golf and Country Club	Bioretention basin, 9 parking lot catch basins with fossil filter filtering devices
CS Bio Co	20 Kelly Ct	Hibiscus Properties LLC	2 bioretention basins
Facebook	1 Facebook Way	Giant Properties LLC	37 bioretention basins
Brilliant Homes Inc	162-164 Jefferson Dr	Murphy Road Apartments – San Jose	6 bioretention areas, 1 flow-through planter

⁴¹ “Newly Installed” includes those facilities for which the final installation inspection was performed during this reporting year.

⁴² State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2). ►Table of Newly Installed⁴¹ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible ⁴² For Maintenance	Type of Treatment/HM Control(s)
Estate Drive	1 Alp Way	The Helsing Group	Bio Swale
Green Hills Country Club	500 Ludeman Lane Unit 1	Watt Barrett	Vortex Separator
Green Hills Country Club	500 Ludeman Lane Unit 2	Watt Barrett	Vortex Separator
Green Hills Country Club	500 Ludeman Lane Unit 3	Watt Barrett	Vortex Separator

⁴¹ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.

⁴²State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2). ►Table of Newly Installed⁴⁰ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible ⁴¹ For Maintenance	Type of Treatment/HM Control(s)
Franklin 299 Apartment Homes	299 Franklin (formerly 145 Monroe) Redwood City, CA 94063	Elan Redwood City, LLC	Media Filters
Indigo Apartment Homes	525 Middlefield Redwood City, CA 94063	Downtown RWC Res, LLC	Flow-Through Planters, Media Filters
Classics Condominium Homes	755 Brewster Redwood City, CA 94063	Classic RWC 1856, L.P.	Media Filters
County Jail	1300 Maple Redwood City, CA 94063	Deborah J. Bazan, Project Director for San Mateo County	Bioretention areas, permeable pavers
Kensington Assisted Living Facility	2808 El Camino Real Redwood City, CA 94063	FSDW-Redwood City, LLC	Bioretention areas
Locale Apartment Homes	488 Winslow (formerly 601 Brewster) Redwood City, CA 94063	The Acclaim Companies	Media Filters
Rossi Lane, Lot 1	318 W Oakwood Blvd Redwood City, CA 94063	Homeowner	Bioretention area
Rossi Lane, Lot 2	18 Rossi Lane Redwood City, CA 94063	Homeowner	Bioretention area
Rossi Lane, Lot 5	11 Rossi Lane Redwood City, CA 94063	Homeowner	Bioretention area
Rossi Lane, Lot 6	328 W Oakwood Blvd	Homeowner	Bioretention area

⁴⁰ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.

⁴¹ State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2). ► Table of Newly Installed⁴⁰ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible ⁴¹ For Maintenance	Type of Treatment/HM Control(s)
	Redwood City, CA 94063		
1022 10 th Avenue	1022 10 th Avenue Redwood City, CA 94063	10 th Avenue Partners, LLC	Bioretention area
Crossing 900	900 Middlefield Redwood City, CA 94063	Hunter/Storm LLC	Media Filters & Bioretention areas
Bristol Meyers	740 Bay Road Redwood City, CA 94063	Bristol Meyers John Bonanno, Executive VP, Investments & Development	Bioretention areas

C.3.h.v.(2). ► Table of Newly Installed⁴¹ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible⁴² For Maintenance	Type of Treatment/HM Control(s)
Orchard Supply & Hardware	360 Industrial Road	Orchard Supply & Hardware	Bio-retention
Lyngso	345 Shoreway Road	San Carlos Industrial Enterprises, LLC	Bio-retention

⁴¹ “Newly Installed” includes those facilities for which the final installation inspection was performed during this reporting year.⁴² State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2). ► Table of Newly Installed⁴⁰ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible⁴¹ For Maintenance	Type of Treatment/HM Control(s)
Century Parking Garage	1400 & 1450 Fashion Island Blvd, San Mateo, CA	Property Owner	Bioretention
Delaware Pacific	1900 S. Delaware St, San Mateo, CA	Property Owner	Bioretention
Hacienda Mateo	701 2 nd Avenue, San Mateo, CA	Property Owner	Bioretention

⁴⁰ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.⁴¹ State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2). ► Table of Newly Installed⁴¹ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible ⁴² For Maintenance	Type of Treatment/HM Control(s)
101 Oyster Point Blvd.	101 Oyster Point Blvd. South San Francisco Ca. 94080	HCP life Sciences	Bio-retention areas
3573 Callan Blvd.	3573 Callan Blvd. South San Francisco Ca. 94080	Seafood City, Inc.	Bio-retention area
Genentech, Inc.	1475 Grandview Dr. South San Francisco Ca. 94080	Genentech, Inc.	Bio-retention area

⁴¹ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.

⁴² State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2). ► Table of Newly Installed⁴⁰ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible ⁴¹ For Maintenance	Type of Treatment/HM Control(s)
Saint Leos Apartments (St. Francis Center)	2626 Marlborough Avenue, North Fair Oaks	Property Owner	Bio-retention Area
SIRI Development – 2 Lot Residential Subdivision	799 Berkeley Avenue, Menlo Park	Property Owner	Bio-retention Area
The Peninsula School	920 Peninsula Way, Menlo Park	Property Owner	Bio-retention Area
Peninsula Golf and Country Club - Clubhouse	701 Madera Drive, San Mateo	Property Owner	Bio-retention Area

⁴⁰ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.

⁴¹ State the responsible operator for installed stormwater treatment systems and HM controls.