

**Stormwater Treatment Measures and Hydromodification Management Controls
Installed within San Mateo County
from July 1, 2016 through June 30, 2017**

The following pages include listings of stormwater treatment measures and any hydromodification controls that were installed in the jurisdictions within San Mateo County from July 1, 2016 through June 30, 2017.

A table is provided for each agency in which stormwater treatment measures and/or HM controls were installed during this timeframe. Some tables also list facilities that were installed prior to this timeframe. Tables are provided for the following agencies:

- Burlingame
- Colma
- Daly City
- East Palo Alto
- Foster City
- Half Moon Bay
- Menlo Park
- Millbrae
- Redwood City
- City of San Mateo
- County of San Mateo (Unincorporated)
- South San Francisco

The following agencies had no stormwater treatment measures or HM controls installed from July 1, 2016 through June 30, 2017, and therefore no table is provided for:

- Atherton
- Belmont
- Brisbane
- Hillsborough
- Pacifica
- Portola Valley
- San Bruno
- San Carlos
- San Mateo County Flood Control District
- Woodside

C.3.h.v.(2) ► Table of Newly Installed³⁸ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible³⁹ For Maintenance	Type of Treatment/HM Control(s)
Peninsula Hospital	1783 El Camino Real	Property Owner	Parking lot bioswales, detention pipes

³⁸ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.³⁹State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2) ► Table of Newly Installed²⁷ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Name of Facility	Address of Facility	Party Responsible²⁸ For Maintenance	Type of Treatment/HM Control(s)
Hills of Eternity (Cemetery)	1299 El Camino Real, Town of Colma, CA	Hills of Eternity Jewish Cemeteries of San Francisco	Bioretention Facility

²⁷ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.

²⁸ State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2) ► Table of Newly Installed³⁸ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible ³⁹ For Maintenance	Type of Treatment/HM Control(s)
Crestview Estates	302 Crestview Circle, Daly City, CA 94015	Brent Reed – Lennar Homes	Bioretention
Steak 'N Shake	362 East Market Street, Daly City, CA 94014	Frank Carraro - Owner	Bioretention
AU Energy Shell	390 Hickey Boulevard, Daly City, CA 94015	Sunny Goyal - Owner	Flow-Through Planter
AU Energy Shell	398 Gellert Boulevard, Daly City, CA 94015	Sunny Goyal - Owner	Flow-Through Planter
Valero	505 Skyline Drive, Daly City, CA 94015	Dean Najdawi - Owner	Flow-Through Planter
Republic Services	1685 Edgeworth Avenue, Daly City, CA 94015	Edward Fusch - Owner	Flow-Through Planter
Mid-Peninsula, The Farm	6800 Mission Street, Daly City, CA 94014	Polo Munoz - Owner	Vault-Based Filter Flow-Through Planter

³⁸ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.³⁹ State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2) ► Table of Newly Installed³⁷ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible ³⁸ For Maintenance	Type of Treatment/HM Control(s)
Senior Housing Mid Peninsula	2358 Univerity Ave	Mid Penn Housing	Bioretention
Cavallino Collision/ Fix It Auto	1874/1880/1884? W Bayshore Rd	Ric Donofrio	Treatment Trench (previously installed in 2008, without O&M Agreement)
Sobrato	2100 University Ave	Sobrato Organization	Flow Through Planters

³⁷ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.

³⁸ State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2) ► Table of Newly Installed³⁸ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible ³⁹ For Maintenance	Type of Treatment/HM Control(s)
Foster Square – MidPen Affordable	790 Alma Lane 1100 Foster Square Lane	Midpen Housing Foster Square Association	Flow-Through Planters; Landscape Areas; Media Filtration

³⁸ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.³⁹ State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2) ► Table of Newly Installed³⁸ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible³⁹ For Maintenance	Type of Treatment/HM Control(s)
Cunha Middle School Gym	600 Church Street	Cabrillo Unified School District	Bioretention Facility
Pilarcitos High School (Hatch School Addition and Modernization)*	498 Kelly Avenue	Cabrillo Unified School District	Bioretention Facility
Fire Department Training Lot*	1191 Main Street, Higgins Canyon Road	Coastside Fire Protection District	Bioretention Facility

*Note: Portions of these projects are still under construction, but the bioretention areas on the Fire Department Training Lot are active, and all but one of the bioretention areas at the Pilarcitos High School site are active.

³⁸ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.

³⁹ State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2). ► Table of Newly Installed²³ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible²⁴ For Maintenance	Type of Treatment/HM Control(s)
Menlo Business Park	1315 O'Brien Drive	Tarlton Properties	3 Self-retaining areas, 1 bio-retention area, 7 flow-through planters
Greenheart Apartments	777 Hamilton Ave	Bayfront Investments, LLC	19 bio-retention areas
MPK23	1 Facebook Way	Facebook	2 bio-retention areas
Mid-Penninsula Housing	1221 Willow Ave	Mid-Penninsula Housing	10 bio-retention areas

²³ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.

²⁴ State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2) ► Table of Newly Installed³⁸ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible³⁹ For Maintenance	Type of Treatment/HM Control(s)
Estate Drive	1 Alp Way	The Helsing Group	Bio Swale
Green Hills Country Club	500 Ludeman Lane, Unit 1	Watt Barrett	Vortex Separator
Green Hills Country Club	500 Ludeman Lane, Unit 2	Watt Barrett	Vortex Separator
Green Hills Country Club	500 Ludeman Lane, Unit 3	Watt Barrett	Vortex Separator

³⁸ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.

³⁹ State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2) ► Table of Newly Installed³⁸ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible ³⁹ For Maintenance	Type of Treatment/HM Control(s)
Delucchi's Market	3636 Florence Street Redwood City, CA 94063	Delucchi Marsh Manor Management, LLC	Bioretention area
Rossi Lane, Lot 3	28 Rossi Lane Redwood City, CA 94063	Homeowner	Bioretention area
Rossi Lane, Lot 4	21 Rossi Lane Redwood City, CA 94063	Homeowner	Bioretention area
Courtyard Marriot	600 Bair Island Road Redwood City, CA 94063	Redwood City Hotels, LLC	Bioretention areas
La Palma	1675 Kentfield Redwood City, CA 94063	La Palma Development, LLC	Bioretention areas, Permeable Pavers
Main & Marshall	601 Main Street Redwood City, CA 94063	LMI Redwood City Holdings, LLC	Media Filters
Westpoint Harbor	1529 Seaport Boulevard Redwood City, CA 94063	Westpoint Harbor, LLC	Bioretention area, vegetated swale

³⁸ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.

³⁹ State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2) ► Table of Newly Installed³⁸ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible ³⁹ For Maintenance	Type of Treatment/HM Control(s)
Clearview Business Park	3005 & 3025 Clearview Way	Embarcadero Capital Partners, LLC	Bioretention & Flo-Thru Planters
Classics at Midtown Place	106-120 Tilton Avenue	Tilton Place, LP	Bioretention & Media Filters
(installed prior to FY 15/16)			
St. Matthews Catholic School	1 Notre Dame	St. Matthews Catholic School	Vegetated swales around perimeter of redeveloped area (Gymnasium)
The Nueva School	131 E. 28th Ave	The Nueva School	Infiltration planters & off-site facility (Detention Pond for Bay Meadows)

³⁸ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.

³⁹ State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2) ► Table of Newly Installed³⁸ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible³⁹ For Maintenance	Type of Treatment/HM Control(s)
Grove Subdivision - 1003 Lakeview	1003 Lakeview Way, Redwood City	Property Owner Per O&M Agreement	Bio-Swale and Catch Basins
Scala Development (Special Project)	302-364 F Street, Colma	Property Owner Per O&M Agreement	Tree Well Filters, Pervious Pavers, and Self-Retaining Areas
Pomponio Ranch	3300 Pomponio Creek Rd, San Gregorio	Property Owner Per O&M Agreement	Flow-through Device, Detention Basin
Peninsula Golf - Maintenance Yard	701 Madera Drive, San Mateo	Property Owner Per O&M Agreement	Vegetated Swales, Bio-Treatment Areas, and Catch Basins
County Live Fire Range	1601 Coyote Point Drive, San Mateo	County per County O&M Policy	Bio-retention Area

³⁸ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.³⁹ State the responsible operator for installed stormwater treatment systems and HM controls.

C.3.h.v.(2) ► Table of Newly Installed³⁸ Stormwater Treatment Systems and Hydromodification Management (HM) Controls (Optional)

Fill in table below or attach your own table including the same information.

Name of Facility	Address of Facility	Party Responsible ³⁹ For Maintenance	Type of Treatment/HM Control(s)
Genentech, Inc. B34	340 DNA Way, South San Francisco, Ca 94080	Genentech, Inc.	Bio-retention area
Fremont Frontier Motel General Partnership	180 S. Airport Blvd., South San Francisco, CA 94080	Fremont Frontier Motel General Partnership	Bio-retention area
City Ventures	1256 Mission Road, South San Francisco, CA 94080	City Ventures Homebuilding, Inc.	Bio-retention area Flow-through Planter Vault
Prologis	175 Sylvester Road, South San Francisco, CA 94080	Prologis, LLC	Bio-retention area

³⁸ "Newly Installed" includes those facilities for which the final installation inspection was performed during this reporting year.

³⁹ State the responsible operator for installed stormwater treatment systems and HM controls.