



Esri, HERE, DeLorme, MapmyIndia, © OpenStreetMap contributors, and the GIS user community

City of Belmont -

Trash Control Status of Land Areas >10,000 ft² Draining Directly to the MS4

Version 1.0 - September 2018

Trash Control Status (Virtual OVTA Score)

- Low
- Moderate
- High
- Very High
- Unknown

All Identified Properties:

- Contain a private storm drain network
- >10,000 square feet of non-building area
- Not treated by trash full capture systems
- Have moderate, high, or very high baseline levels of trash generation

